

Drillhole Reference: BH1204 Date Drilled: 21/02/2023 Photographed By: BW/RC Date Photographed: 22/02/2023



Box 11 - Depth: 26.1 to 28.2m



Box 12 - Depth: 28.2 to 30.5m



Drillhole Reference: BH1204 Date Drilled: 21/02/2023 Photographed By: BW/RC Date Photographed: 22/02/2023



Box 13 - Depth: 30.5 to 32.6m



Box 14 - Depth: 32.6 to 34.5m



Drillhole Reference: BH1204 Date Drilled: 22/02/2023 Photographed By: BW/RC Date Photographed: 23/02/2023



Box 15 - Depth: 34.5 to 37.1m



Box 16 - Depth: 37.1 to 39.3m



Drillhole Reference: Photographed By:

BH1204 BW/RC

Date Drilled: Date Photographed:





Drillhole Reference: BH1205A Date Drilled: 16/03/2023 Photographed By: Date Photographed: 17/03/2023



Box 1 - Depth: 0.00 to 4.5m



Box 2 - Depth: 4.50 to 7.5m



Drillhole Reference: BH1205A Date Drilled: 16/03/2023 Photographed By: Date Photographed: 17/03/2023



Box 3 - Depth: 7.50 to 10.5m



Box 4 - Depth: 10.50 to 12.6m



Drillhole Reference: BH1205A Date Drilled: 20/03/2023 Photographed By: BW/RC Date Photographed: 21/03/2023



Box 5 – Depth: 12.6 to 14.67m



Box 6 – Depth: 14.67 to 16.8m



Drillhole Reference: Photographed By:

BH1205A BW/RC Date Drilled: Date Photographed: 20/03/2023 21/03/2023



Box 7 - Depth: 16.8 to 19.1m



Box 8 - Depth: 19.1 to 21.0m



Drillhole Reference: Photographed By:

BH1205A BW/RC Date Drilled: Date Photographed: 20/03/2023 21/03/2023



Box 9 - Depth: 21.0 to 22.9m



Box 10 - Depth: 22.9 to 25.1m



Drillhole Reference: BH1205A Date Drilled: 20/03/2023 Photographed By: BW/RC Date Photographed: 21/03/2023



Box 11 - Depth: 25.1 to 27.2m



Box 12 - Depth: 27.2 to 29.4m



Drillhole Reference: BH1205A Date Drilled: 21/03/2023 Photographed By: BW/RC Date Photographed: 22/03/2023



Box 13 - Depth: 29.4 to 31.5m



Box 14 - Depth: 31.5 to 33.4m



Drillhole Reference: BH1205A Date Drilled: 21/03/2023 Photographed By: BW/RC Date Photographed: 22/03/2023



Box 15 - Depth: 33.4 to 35.2m



Box 16 - Depth: 35.2 to 37.5m



Drillhole Reference: BH1205A Date Drilled: 21/03/2023 Photographed By: BW/RC Date Photographed: 22/03/2023



Box 17 - Depth: 37.5 to 39.63m



Box 18 - Depth: 39.63 to 42.3m



Drillhole Reference: Photographed By:

BH1205A BW/RC Date Drilled: Date Photographed: 22/03/2023 23/03/2023



Box 19 - Depth: 42.3 to 44.3m



Box 20 - Depth: 44.3 to 46.5m



Drillhole Reference: Photographed By:

BH1205A BW/RC Date Drilled: Date Photographed: 22/03/2023 23/03/2023



Box 21 - Depth: 46.5 to 48.8m



Box 22 - Depth: 48.8 to 50.15m



Drillhole Reference: Photographed By:

BH1206 BW/RC Date Drilled:
Date Photographed:



Box 1 – Depth: 0.00 to 2.70m



Box 2 – Depth: 2.7 to 4.70m



Drillhole Reference: BH1206 Date Drilled: 24/02/2023 Photographed By: BW/RC Date Photographed: 25/02/2023



Box 3 - Depth: 4.7 to 6.9m



Box 4 - Depth: 6.9 to 8.85m



Drillhole Reference: BH1206 Date Drilled: 24/02/2023 Photographed By: BW/RC Date Photographed: 25/02/2023



Box 5 - Depth: 8.85 to 10.8m



Box 6 – Depth: 10.8 to 12.7m



Drillhole Reference: BH1206 Date Drilled: 24/02/2023 Photographed By: BW/RC Date Photographed: 25/02/2023



Box 7 - Depth: 12.7 to 15.0m



Box 8 - Depth: 15.0 to 18.0m



Drillhole Reference: BH1206 Date Drilled: 27/02/2023 Photographed By: BW/RC Date Photographed: 28/02/2023



Box 9 - Depth: 18.0 to 20.5m



Box 10 - Depth: 20.5 to 23.1m



Drillhole Reference: BH1206 Date Drilled: 27/02/2023 Photographed By: BW/RC Date Photographed: 28/02/2023



Box 11 - Depth: 23.1 to 25.5m



Box 12 - Depth: 25.5 to 28.0m



Drillhole Reference: BH1206 Date Drilled: 27/02/2023 Photographed By: BW/RC Date Photographed: 28/02/2023



Box 13 - Depth: 28.0 to 30.85m



Box 14 - Depth: 30.85 to 33.3m



Drillhole Reference: BH1206 Date Drilled: 28/02/2023 Photographed By: BW/RC Date Photographed: 29/02/2023



Box 15 - Depth: 33.3 to 35.52m



Box 16 - Depth: 35.52 to 37.65m



Drillhole Reference: BH1206 Date Drilled: 28/02/2023 Photographed By: BW/RC Date Photographed: 29/02/2023



Box 17 - Depth: 37.65 to 40.0m



Box 18 - Depth: 40.0 to 42.25m



Drillhole Reference: Photographed By:

BH1206 BW/RC Date Drilled: Date Photographed: 01/03/2023 02/03/2023



Box 19 - Depth: 42.25 to 44.6m



Box 20 - Depth: 44.6 to 46.8m



Drillhole Reference: Photographed By:

BH1206 BW/RC Date Drilled: Date Photographed: 01/03/2023 02/03/2023



Box 21 - Depth: 46.8 to 49.0m



Box 22 - Depth: 49.0 to 50.2m



Drillhole Reference: BH1207 Date Drilled: 22/02/2023 Photographed By: BW/RC Date Photographed: 23/02/2023



Box 1 – Depth: 0.00 to 2.0m



Box 2 - Depth: 2.00 to 4.2m



Drillhole Reference: BH1207 Date Drilled: 22/02/2023 Photographed By: BW/RC Date Photographed: 23/02/2023



Box 3 - Depth: 4.20 to 6.0m



Box 4 – Depth: 6.0 to 10.95m



Drillhole Reference: BH1207 Date Drilled: 23/02/2023 Photographed By: BW/RC Date Photographed: 24/02/2023



Box 5 - Depth: 10.95 to 13.50m



Box 6 - Depth: 13.50 to 16.50m



Drillhole Reference: BH1207 Date Drilled: 24/02/2023 Photographed By: BW/RC Date Photographed: 25/02/2023



Box 7 - Depth: 16.50 to 18.35m



Box 8 - Depth: 18.35 to 20.5m



Drillhole Reference: BH1207 Date Drilled: 24/02/2023 Photographed By: BW/RC Date Photographed: 25/02/2023



Box 9 - Depth: 20.5 to 22.5m



Box 10 – Depth: 22.5 to 24.65m



Drillhole Reference: Photographed By:

BH1207 BW/RC

Date Drilled: Date Photographed:



Box 11 - Depth: 24.65 to 26.60m



Box 12 - Depth: 26.60 to 28.90m



Drillhole Reference: Photographed By:

BH1207 BW/RC Date Drilled: Date Photographed:



Box 13 - Depth: 28.90 to 31.2m



Box 14 - Depth: 31.2 to 33.0m



Drillhole Reference: Photographed By:

BH1207 BW/RC Date Drilled: Date Photographed:



Box 15 - Depth: 33.0 to 35.6m



Box 16 - Depth: 35.6 to 37.75m



Drillhole Reference: BH1207 Date Drilled: 27/02/2023 Photographed By: BW/RC Date Photographed: 28/02/2023



Box 17 – Depth: 37.75 to 39.82m



Box 18 - Depth: 39.82 to 40.5m



Drillhole Reference: BH1208 Date Drilled: 30/03/2023 Photographed By: BW/RC Date Photographed: 31/03/2023



Box 1 - Depth: 0.00 to 4.5m



Box 2 - Depth: 4.5 to 7.24m



Drillhole Reference: BH1208 Date Drilled: 30/03/2023 Photographed By: BW/RC Date Photographed: 31/03/2023



Box 3 – Depth: 7.24 to 9.76m



Box 4 - Depth: 9.76 to 12.0m



Drillhole Reference: BH1208 Date Drilled: 31/03/2023 Photographed By: BW/RC Date Photographed: 01/04/2023



Box 5 - Depth: 12.0 to 14.2m



Box 6 - Depth: 14.2 to 17.03m



Drillhole Reference: BH1208 Date Drilled: 03/04/2023 Photographed By: Date Photographed: 04/04/2023



Box 7 - Depth: 17.03 to 19.50m



Box 8 - Depth: 19.50 to 22.2m



Drillhole Reference: BH1208 Date Drilled: 05/04/2023 Photographed By: Date Photographed: 06/04/2023



Box 9 - Depth: 22.2 to 25.0m



Box 10 - Depth: 25.0 to 27.0m



Drillhole Reference: Photographed By:

BH1208 BW/RC Date Drilled: Date Photographed: 05/04/2023 06/04/2023



Box 11 - Depth: 27.0 to 29.3m



Box 12 - Depth: 29.3 to 31.85m



Drillhole Reference: Photographed By:

BH1208 BW/RC Date Drilled: Date Photographed: 05/04/2023 06/04/2023



Box 13 - Depth: 31.85 to 34.8m



Box 14 - Depth: 34.8 to 36.90m



Drillhole Reference: BH1208 Date Drilled: 06/04/2023 Photographed By: BW/RC Date Photographed: 07/04/2023



Box 15 - Depth: 36.90 to 39.0m



Box 16 - Depth: 39.0 to 41.3m



Drillhole Reference: Photographed By:

BH1208 BW/RC Date Drilled:
Date Photographed:

06/04/2023 07/04/2023



Box 17 - Depth: 41.3 to 43.5m



Box 18 - Depth: 43.5 to 46.05m



Drillhole Reference: BH1208 Date Drilled: 06/04/2023 Photographed By: BW/RC Date Photographed: 07/04/2023



Box 19 - Depth: 46.05 to 47.65m



Box 20 - Depth: 47.65 to 49.87m



Drillhole Reference: Photographed By:

BH1208 BW/RC

Date Drilled: Date Photographed:

06/04/2023 07/04/2023





Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled:
Date Photographed:



Box 1 – Depth: 0.00 to 3.80m




Box 2 - Depth: 3.80 to 6.0m



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed:







Box 4 - Depth: 8.2 to 10.2m#



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed:



Box 5 - Depth: 10.2 to 12.2m



Box 6 - Depth: 12.2 to 14.3m



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled:
Date Photographed:



Box 7 - Depth: 14.3 to 16.4m



Box 8 - Depth: 16.4 to 18.25m



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed:



Box 9 - Depth: 18.25 to 20.2m#



Box 10 - Depth: 20.2 to 22.2m#



Drillhole Reference: BH1209 Date Drilled: 12/04/2023 Photographed By: BW/RC Date Photographed: 13/04/2023



Box 11 - Depth: 22.2 to 24.0m



Box 12 - Depth: 24.0 to 26.1m



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed: 13/04/2023 14/04/2023



Box 13 - Depth: 26.1 to 28.05m#



Box 14 - Depth: 28.05 to 30.0m#

#



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed:



Box 15 - Depth: 30.0 to 32.2m#



Box 16 - Depth: 32.2 to 34.1m#



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed:



Box 17 - Depth: 34.1 to 37.1m#



Box 18 - Depth: 37.1 to 39.45m#



Drillhole Reference: Photographed By: BH1209 BW/RC Date Drilled: Date Photographed:



Box 19 - Depth: 39.45 to 41.7m#



Box 20 - Depth: 41.7 to 43.5m#



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed:



Box 21 - Depth: 43.5 to 46.0m#



Box 22 - Depth: 46.0 to 48.35m#



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed:



Box 23 - Depth: 48.35 to 50.77m#



Box 24 - Depth: 50.77 to 53.1m#



17/04/2023

18/04/2023

Auckland Light Rail: Stage 1 GI

Drillhole Reference: BH1209 Date Drilled: Photographed By: BW/RC Date Photographed:



Box 25 - Depth: 53.1 to 55.25m#



Box 26 - Depth: 55.25 to 57.5m#



Drillhole Reference: Photographed By:

BH1209 BW/RC Date Drilled: Date Photographed:



Box 27 - Depth: 57.5 to 59.45m#



Box 28 - Depth: 59.45 to 60.0m#



Drillhole Reference: Photographed By:

BH1209A BW/RC

Date Drilled: Date Photographed:



Box 01 - Depth: 0.0 to 5.1m



Box 02 - Depth: 5.1 to 7.9m



Drillhole Reference: Photographed By:

BH1209A BW/RC

Date Drilled: Date Photographed:



Box 03 - Depth: 7.9 to 10.5m



Box 04 - Depth: 10.5 to 13.1m



Drillhole Reference: Photographed By:

BH1209A BW/RC

Date Drilled: Date Photographed:



Box 05 - Depth: 13.1 to 15.65m



Box 06 - Depth: 15.65 to 18.0m



Drillhole Reference: Photographed By:

BH1209A BW/RC Date Drilled: Date Photographed:



Box 07 - Depth: 18.0 to 20.55m



Box 08 - Depth: 20.55 to 23.05m



Drillhole Reference: Photographed By:

BH1209A BW/RC

Date Drilled: Date Photographed:



Box 09 - Depth: 23.05 to 25.5m



Box 10 - Depth: 25.5 to 28.1m



Drillhole Reference: Photographed By:

BH1209A BW/RC

Date Drilled: Date Photographed:



Box 11 - Depth: 28.1 to 30.6m



Box 12 - Depth: 30.6 to 33.25m



Drillhole Reference: Photographed By:

BH1209A BW/RC Date Drilled: Date Photographed:



Box 13 - Depth: 33.25 to 35.7m



Box 14 - Depth: 35.7 to 38.55m



Drillhole Reference: Photographed By:

BH1209A BW/RC

Date Drilled: Date Photographed: 10/07/2023 11/07/2023



Box 15 - Depth: 38.55 to 41.49m



Box 16 - Depth: 41.4 to 44.4m



Drillhole Reference: **BH1209A** Date Drilled: 10/07/2023 11/07/2023 BW/RC Photographed By: Date Photographed: SPACER



Drillhole Reference: BH1210 Date Drilled: 02/05/2023 Photographed By: BW/RC Date Photographed: 03/05/2023



Box 01 - Depth 8.15 to 11.33m



Box 02 - Depth 8.15 to 11.33m



Drillhole Reference: BH1210 Date Drilled: 02/05/2023 Photographed By: BW/RC Date Photographed: 03/05/2023



Box 03 - Depth 8.15 to 11.33m



Box 04 - Depth 8.15 to 11.33m



Drillhole Reference: BH1210 Date Drilled: 02/05/2023 Photographed By: BW/RC Date Photographed: 03/05/2023



Box 05 - Depth 8.15 to 11.33m



Box 06 - Depth 8.15 to 11.33m